Submit a Manuscript: https://www.f6publishing.com

World J Clin Cases 2023 October 26; 11(30): 7393-7397

DOI: 10.12998/wjcc.v11.i30.7393 ISSN 2307-8960 (online)

CASE REPORT

Lead helix winding tricuspid chordae tendineae: A case report

Teng-Fei Liu, Chun-Hua Ding

Specialty type: Cardiac and cardiovascular systems

Provenance and peer review:

Unsolicited article; Externally peer reviewed.

Peer-review model: Single blind

Peer-review report's scientific quality classification

Grade A (Excellent): 0 Grade B (Very good): B Grade C (Good): 0 Grade D (Fair): 0 Grade E (Poor): 0

P-Reviewer: Sharma D, India

Received: June 24, 2023 Peer-review started: June 24, 2023 First decision: August 9, 2023 Revised: September 7, 2023 Accepted: September 11, 2023 Article in press: September 11, 2023 Published online: October 26, 2023



Teng-Fei Liu, Chun-Hua Ding, Cardiac Department, Aerospace Center Hospital, Peking University Aerospace School of Clinical Medicine, Beijing 100049, China

Corresponding author: Chun-Hua Ding, MD, PhD, Chief Physician, Director, Cardiac Department, Aerospace Center Hospital, Peking University Aerospace School of Clinical Medicine, No. 15 Yuquan Road, Haidian District, Beijing 100049, China. dingmd@gmail.com

Abstract

BACKGROUND

As left bundle branch pacing (LBBP) is more like physiological pacing, LBBP has emerged as a novel pacing strategy that uses the native conduction system to improve ventricular synchronization with stable pacing parameters. LBBP has been revealed associated with a significantly reduced risk of new-onset atrial fibrillation and heart failure compared with conventional permanent pacemaker implantation.

CASE SUMMARY

A 64-year-old man was admitted with a 24-h history of chest distress and shortness of breath, which continued unabated. The patient had no symptoms of chest pain, dizziness, syncope, nausea nor vomiting. There were no abnormalities found in routine examinations after admission. Twelve-lead electrocardiogram presented a result of 2:1 atrioventricular block. Coronary angiography was performed the next day and no abnormality was found. Finally, the patient agreed to received LBBP and signed the informed consent. During the process of withdrawing the Medtronic Model 3830 lead into sheath, we found the lead helix was wrapped around the chordae tendineae of the septal valve of tricuspid. Attempts to rotate the 3830 lead failed to release the lead helix from the chordae tendineae, and ultimately we used radiofrequency ablation to ablate the wrapped chordae tendineae.

CONCLUSION

Radiofrequency ablation effectively solved this problem without complications. It is an effective and reliable method to resolve lead winding chordae.

Key Words: Pacemaker, Left bundle branch pacing; Lead; Tricuspid; Chordae tendineae; Radiofrequency ablation; Case report

©The Author(s) 2023. Published by Baishideng Publishing Group Inc. All rights reserved.

Core Tip: Radiofrequency ablation can be used to separate the lead helix from a wrapped chordae tendineae. This method helped our patient avoid a surgical procedure. The innovation of this novel technique is its use of a high concentration of saline (10% NaCl) to reduce impedance.

Citation: Liu TF, Ding CH. Lead helix winding tricuspid chordae tendineae: A case report. World J Clin Cases 2023; 11(30): 7393-

URL: https://www.wjgnet.com/2307-8960/full/v11/i30/7393.htm

DOI: https://dx.doi.org/10.12998/wjcc.v11.i30.7393

INTRODUCTION

As left bundle branch pacing (LBBP) is more like physiological pacing, LBBP has emerged as a novel pacing strategy that uses the native conduction system to improve ventricular synchronization with stable pacing parameters. LBBP has been revealed associated with a significantly reduced risk of new-onset atrial fibrillation and heart failure compared with conventional permanent pacemaker implantation[1].

In our experience with lead implantation of the Medtronic Model 3830 (Minneapolis, MN, United States), we encountered a problem. The pacing position was not ideal, and the intracardiac electrocardiogram (ECG) indicated Q waves in the inferior wall leads (II III AVF). Our aim was to adjust the lead position to get a good parameter. During the process of withdrawing the 3830 lead to sheath, however, we found the lead helix was wrapped around the chordae tendineae of the septal valve of tricuspid. We performed a right ventricular angiography immediately (Figure 1). We rotated the lead clockwise as well as counterclockwise, and in the meantime sent the 3830 lead forward as well as backward while adjusting the sheath tube forward for sending or withdrawal at different angles. After nearly 2 h of attempts, we failed to release the lead helix from the chordae tendineae.

Finally, we used radiofrequency ablation to ablate the wrapped chordae tendineae. We connected the tip of the ablation catheter to the end of the 3830 lead (cathode ring). In this manner, the ablation catheter, the 3830 lead with the winding chordae tendineae, and the back electrode plate of the patient linked with the radiofrequency generator formed a closed current loop (Figure 2). Radiofrequency energy successfully transmitted to the tip of the 3830 lead. Unfortunately, the radiofrequency generator failed to work as the impedance was over the maximum (350 ohms) allowed.

We then tried to add another back electrode to reduce the impedance from 350 ohms to 300 ohms. But it failed to discharge, again because of the high impedance. Finally, a high concentration of saline (10% NaCl) was injected into the sheath of the electrode (Supplementary Figure 1) and the impedance was reduced from 300 ohms to 125 ohms. During the 3-s abatement, the lead helix successfully separated from the chordae tendineae.

We changed to a new Model 3830 electrode and successfully implanted it into the left bundle branch area, with good capture threshold and pacing pattern (Figure 3). After that, we performed a reexamination by ECG and discovered a mild regurgitation signal of tricuspid and pericardial effusion. The patient had no complaint of discomfort.

The pacemaker was programmed before the patient was discharged, and the pacing threshold, sense, and impedance were good. The patient was regularly followed up in the clinic and the pacemaker worked normally.

CASE PRESENTATION

Chief complaints

A 64-year-old man was admitted with a 24-h history of chest distress and shortness of breath. The patient had no symptoms of chest pain, dizziness, syncope, nausea nor vomiting.

History of present illness

Symptoms started 24 h before, with no reason. The patient was consequently sent to the Emergency Room of Aerospace Center Hospital, Peking University Aerospace School of Clinical Medicine.

History of past illness

The patient had a 14-year history of hypertension. The highest blood pressure recorded was 150/90 mmHg. Valsartan was taken regularly and controlled the blood pressure well.


Personal and family history

The patient denied any family history of disease.

Physical examination


Body temperature, 36.5 °C; blood pressure, 108/65 mmHg; heart rate, 38 beats per min; respiratory rate, 18 breaths per min.





DOI: 10.12998/wjcc.v11.i30.7393 **Copyright** ©The Author(s) 2023.

Figure 1 Right ventricular angiography showed the lead helix wound with the chordae tendineae. A: LAO 30°; B: RAO 30°.



DOI: 10.12998/wjcc.v11.i30.7393 **Copyright** ©The Author(s) 2023.

Figure 2 Loop schematic diagram of the chordae tendineae was ablated by radiofrequency electricity through the tip of the Model 3830 lead (radiofrequency generator-ablation catheter-3830 lead tip-chordae tendineae-blood-heart-back electrode plate-radiofrequency generator).

Laboratory examinations

There was no abnormality in routine laboratory examinations made after admission.


Imaging examinations

Twelve-lead ECG presented a result of 2:1 atrioventricular block (AVB) (Supplementary Figure 2). Coronary angiography was performed the next day and no abnormality was found (Supplementary Figure 3).

FINAL DIAGNOSIS

Combined with the patient's medical history and the examinations, the final diagnosis was 2:1 AVB and hypertension.





DOI: 10.12998/wjcc.v11.i30.7393 **Copyright** ©The Author(s) 2023.

Figure 3 Intracardiac electrocardiogram of left bundle branch pacing.

TREATMENT

Permanent pacemaker with LBBP was implanted for the patient. During the process of withdrawing the 3830 leads to the sheath, we found the lead helix was wrapped around the chordae tendineae of the septal valve of the tricuspid. Finally, we used radiofrequency ablation from the 3830 lead helix to ablate the wrapped chordae tendineae.

OUTCOME AND FOLLOW-UP

The patient was regularly followed up at the clinic. The patient had no symptoms of discomfort and an ECG was added (Supplementary Figure 4). The echocardiography showed mild tricuspid regurgitation (Supplementary Figure 5).

DISCUSSION

The present case involved a rare occurrence of a pacemaker lead wrapped around the chordae tendineae. This is the first case to describe how to resolve this problem by radiofrequency ablation with high impedance. We successfully solved this problem using a high concentration of saline (10% NaCl) to reduce the impedance according to Ohm's law[2] and the principles of radiofrequency ablation[3,4]. When the radiofrequency energy was sent to 3830 lead helixes, heat was generated to dehydrate and denature the wrapped chordae tendineae.

Since intracardiac echocardiography was unavailable in the catheter lab which may have shown the wrapping situation of the electrode tip and chordae tendineae, this could have helped to guide us and allow for visualization of a way to rotate the lead.

The patient was satisfied with the result of the treatment, and for avoiding mental, financial, and physical damage by iatrogenic injuries.

This case demonstrates how to resolve a Model 3830 lead wrapped around the chordae tendineae.

CONCLUSION

Radiofrequency ablation with the injection of a high concentration of saline in the sheath effectively solves the problem of the Medtronic 3830 lead wrapped around the chordae tendineae without complications.

ACKNOWLEDGEMENTS

We thank all doctors in cardiology for supporting and coordinating with us to get the available data and materials.

FOOTNOTES

Author contributions: Liu TF contributed to manuscript writing, editing, and data collection; Ding CH contributed to the conceptualization and supervision; All authors have read and approved the final manuscript.

Informed consent statement: Informed written consent was obtained from the patient for publication of this report and any accompanying images.

Conflict-of-interest statement: There are no conflicts of interest to disclose.

CARE Checklist (2016) statement: The authors have read the CARE Checklist (2016), and the manuscript was prepared and revised according to the CARE Checklist (2016).

Open-Access: This article is an open-access article that was selected by an in-house editor and fully peer-reviewed by external reviewers. It is distributed in accordance with the Creative Commons Attribution NonCommercial (CC BY-NC 4.0) license, which permits others to distribute, remix, adapt, build upon this work non-commercially, and license their derivative works on different terms, provided the original work is properly cited and the use is non-commercial. See: https://creativecommons.org/Licenses/by-nc/4.0/

Country/Territory of origin: China

ORCID number: Teng-Fei Liu 0000-0001-9711-6218; Chun-Hua Ding 0000-0003-4381-6723.

S-Editor: Liu JH L-Editor: Filipodia P-Editor: Yu HG

REFERENCES

- Zhu H, Li X, Wang Z, Liu Q, Chu B, Yao Y, Liu Z, Xie R, Fan X. New-onset atrial fibrillation following left bundle branch area pacing vs. right ventricular pacing: a two-centre prospective cohort study. Europace 2023; 25: 121-129 [PMID: 35942552 DOI: 10.1093/europace/euac132]
- Anderson WP, Hendrix DL, Higinbotham N. The effect of cyanide and carbon monoxide on the electrical potential and resistance of cell 2 membranes. Plant Physiol 1974; 54: 712-716 [PMID: 16658958 DOI: 10.1104/pp.54.5.712]
- 3 Lavergne T, Sebag C, Ollitrault J, Chouari S, Copie X, Le Heuzey JY, Guize L. [Radiofrequency ablation: physical bases and principles]. Arch Mal Coeur Vaiss 1996; 89 Spec No 1: 57-63 [PMID: 8734165]
- Aerts S, Calderon C, Valič B, Maslanyj M, Addison D, Mee T, Goiceanu C, Verloock L, Van den Bossche M, Gajšek P, Vermeulen R, Röösli M, Cardis E, Martens L, Joseph W. Measurements of intermediate-frequency electric and magnetic fields in households. Environ Res 2017; **154**: 160-170 [PMID: 28086101 DOI: 10.1016/j.envres.2017.01.001]



Published by Baishideng Publishing Group Inc

7041 Koll Center Parkway, Suite 160, Pleasanton, CA 94566, USA

Telephone: +1-925-3991568

E-mail: bpgoffice@wjgnet.com

Help Desk: https://www.f6publishing.com/helpdesk

https://www.wjgnet.com

