



26962-Review

Quotes Included
Bibliography Included18%
SIMILAR

Match Overview



1	Crossref 67 words De Smet, K.. "Revision surgery for failed hip resurfacing", The hip resurfacing handbook, 2013.	5%
2	Crossref 56 words Morlock, M.. "Mismatched wear couple zirconium oxide ar ... aluminum oxide in total hip arthroplasty", The Journal of Ar	4%
3	Internet 32 words crawled on 26-Apr-2009 www.istaonline.org	2%
4	Crossref 31 words Hanks, G.A.. "Total hip arthroplasty complicated by mismat ched implant sizes", The Journal of Arthroplasty, 1986	2%
5	Crossref 20 words Yang, J.. "Changes in Cobalt and Chromium Levels After ... Metal-on-Metal Hip Resurfacing in Young, Active Chinese	1%
6	Crossref 18 words De Smet, K.. "Letter to the Editor Regarding the Article "... p Resurfacing Arthroplasty: The Australian Experience"', T	1%

Name of Journal: *World Journal of Orthopedics*

ESPS Manuscript NO: 26962

Manuscript Type: Case Report

Hip resurfacing arthroplasty complicated by mismatched implant components

Alessandro Calistri, Patricia Campbell, Catherine Van Der Straeten, Koen
Aimè De Smet

Abstract

Metal-on-metal hip resurfacing has gained popularity as a feasible treatment option for young and active patients with hip osteoarthritis and high functional expectations. This procedure should only be performed by surgeons who have trained specifically in this technique. Preoperative planning is essential for hip resurfacing in order to execute a successful operation and preview any technical problems. The authors present a case of a man who underwent a resurfacing arthroplasty for osteoarthritis of the left hip that was complicated by mismatched

[全部](#)[图片](#)[新闻](#)[视频](#)[更多 ▾](#)[搜索工具](#)

找到约 53,400 条结果 (用时 0.63 秒)

Google 学术: Hip Resurfacing Arthroplasty Complicated by Mismatched Implant Components

Resurfacing THA for Patients Younger Than 50 Years: ... - Amstutz - 被引用次数: 123

Current concepts of metal-on-metal hip resurfacing - Clarke - 被引用次数: 56

(iii) Resurfacing arthroplasty of the hip - Roberts - 被引用次数: 21

[PDF] Component Size Mismatch of Metal on Metal Hip Arthropl...

www.arthroplastyjournal.org/article/S0883...X/pdf ▾ 翻译此页

Size mismatch of components used in total hip arthroplasty is a serious, preventable patient safety ... mismatch of orthopaedic implants is one of these Never Events. The ... Resurfacing 54 ... Total hip arthroplasty complicated by mismatched.

Conversion of a failed hip resurfacing arthroplasty to total hip ...

www.ncbi.nlm.nih.gov > ... > Literature > PubMed Central (PMC) - 翻译此页

作者: JA Haynes - 2016

2016年1月23日 - Hip resurfacing, or surface replacement arthroplasty (SRA), has been utilized in ... Femoral neck fracture, acetabular and femoral component ... Benefits of conversion to THA include lack of concern for implant mismatch, and ...

缺少字词: complicated

Hip Resurfacing-OrthoInfo - AAOS

orthoinfo.aaos.org/topic.cfm?topic=A00586 ▾ 翻译此页

Because the components (called implants) used in hip replacements and hip ... This second procedure is called a revision and it can be more complicated than the initial ... Unlike hip replacement, hip resurfacing is not suitable for all patients.

[全部](#)[图片](#)[视频](#)[新闻](#)[更多 ▾](#)[搜索工具](#)

找到约 44,300 条结果 (用时 0.63 秒)

Google 学术: Hip resurfacing arthroplasty complicated by mismatched implant components

[Resurfacing THA for Patients Younger Than 50 Years: ...](#) - [Amstutz](#) - 被引用次数: 120

[Mixing and matching causing taper wear](#) - [Chana](#) - 被引用次数: 44

[Current concepts of metal-on-metal hip resurfacing](#) - [Clarke](#) - 被引用次数: 58

Component Size Mismatch of Metal on Metal Hip Arthroplasty: An ...

https://www.researchgate.net/.../261607054_Component_Size_Mismatch_of... - [翻译此页](#)

Size mismatch of components used in total hip arthroplasty is a serious, preventable patient safety incident of unknown prevalence as mismatch of orthopaedic implants is one of these Never Events. The Plain radiograph of BHR resurfacing with an oversized head. Total hip arthroplasty complicated by mismatched.

Revision of Failed Hip Resurfacing and Large Metal-on-Metal Total ...

www.healio.com/.../revision-of-failed-hip-resurfacing-and-large-metal-on-m... - [翻译此页](#)

作者: N Snir - 2015 - 被引用次数: 2 - 相关文章

2015年6月12日 - Revision of metal-on-metal (MoM) total hip arthroplasty (THA) or hip ... to as high as 49% for the ASR implant (DePuy, Leeds, United Kingdom). Hip resurfacing with a monoblock acetabular component complicated by femoral neck fracture (A). ... Due to size mismatch and issues of modularity, retention of ...

Component Size Mismatch of Metal on Metal Hip Arthroplasty: An ...

www.academia.edu/.../Component_Size_Mismatch_of_Metal_on_Metal_Hi... - [翻译此页](#)

Component Size Mismatch of Metal on Metal Hip Arthroplasty: An Avoidable Never Event. 6 Pages ...

Component mismatch of orthopaedic implants is one of these Never Events. The NHS ... Plain

[全部](#)[图片](#)[视频](#)[购物](#)[新闻](#)[更多](#)[设置](#)[工具](#)

找到约 46,700 条结果 (用时 0.57 秒)

Google 学术: Hip resurfacing arthroplasty complicated by mismatched implant components

Resurfacing THA for Patients Younger Than 50 Years: ... - [Amstutz](#) - 被引用次数: 121

Mixing and matching causing taper wear - [Chana](#) - 被引用次数: 48

Current concepts of metal-on-metal hip resurfacing - [Clarke](#) - 被引用次数: 58

Detection of incorrect manufacturer labelling of hip components - NCBI

<https://www.ncbi.nlm.nih.gov/pmc/articles/PMC5121176/> - 翻译此页

作者: M Durand-Hill - 2017

2016年9月22日 - Surgical notes indicated the appropriate combinations of implants were used. ... Size mismatch of components used in total hip arthroplasty, is a "serious, The explanted Adept hip resurfacing components, both acetabular and femoral Total hip arthroplasty complicated by mismatched implant sizes.

Component Size Mismatch of Metal on Metal Hip Arthroplasty: An ...

https://www.researchgate.net/.../261607054_Component_Size_Mismatch_of... - 翻译此页

2016年10月18日 - Size mismatch of components used in total hip arthroplasty is a serious, preventable patient safety incident of unknown ... mismatch of orthopaedic implants is one of these Never Events. Plain radiograph of BHR resurfacing with an oversized head. Total hip arthroplasty complicated by mismatched.

Total hip arthroplasty complicated by mismatched implant sizes ...

https://www.researchgate.net/.../19601529_Total_hip_arthroplasty_complica... - 翻译此页

Total hip arthroplasty complicated by mismatched implant sizes. ... Two cases are reported in which the